

## Viking Subscriber Software 20.1 Point 2 - AMENDMENT

Release: August 4, 2020

Amendment date: November 18, 2020

**FSN-1120-VIKING-17**

This Field Software Notice (FSN) announces an amendment to the KENWOOD Viking® subscriber software version 20.1 Point 2 release. The original release of 20.1 point 2 included only a minor Armada update to resolve limited scope issues. This amendment covers a minor Viking Firmware update that may have temporarily appeared to Armada Subscription holders in the 20.1 point 2 release sharefile distribution.

### Software Versions

The following table indicates Viking Software items and the corresponding versions considered to be released and available for general use. These represent no change from the original 20.1 point 2 release and 20.1 initial release distribution.

Item	Version – General Release
Armada	1.30.11
Armada Proxy	1.30.7
VP600/900 Firmware Image	8.30.9
VM600/900 Firmware Image	8.30.9
VP5000/6000 Firmware Image	8.30.9
VM5000/6000/7000 Firmware Image	8.30.9
Viking Tune Lite	1.30.6

The below firmware items may have been temporarily available to subscription holders. This included a change specific to a single user that was not deemed necessary to distribute for general availability. However, if you received and used any of the below, we do not expect it to cause any issues and there is no harm if it was unintentionally deployed.

Item	Version – Temporary Release
VP600/900 Firmware Image	8.30.10
VM600/900 Firmware Image	8.30.10
VP5000/6000 Firmware Image	8.30.10
VM5000/6000/7000 Firmware Image	8.30.10

If you have any questions or concerns regarding the temporary release items, please contact technical support at 1-800-328-3911 option 3.

*For questions regarding this Field Service Bulletin, please contact the KENWOOD Viking team at 1.800.328.3911, option 3.*